




## Dual-View Imaging Report




Observations:  
Moisture in sheetrock at risk



Location Floor: Basement  
Location Room: Bedroom


Observations:  
New Item 1, Moisture detected behind Siding.

## Dual-View Imaging Report



Location Floor: Basement  
 Location Room: Bedroom


Observations:  
 Moisture detected behind Siding.



Location Floor: Basement  
 Location Room: Bedroom


Observations:  
 Moisture detected in sheetrock.

## Dual-View Imaging Report



Location Floor: 2nd Floor  
Location Room: Bedroom

Observations:  
Missing Insulation



Location Floor: 1st Floor  
Location Room: Family Room

Observations:  
Radiant ceiling with exposed wood beams.