

# Thermal Evaluation




Tommy Garner HVAC  
123 Your Street  
Newport News, Va. 23606  
Prepared for: Tommy Garner

Prepared by: Southeast Home Inspections, Inc.  
626 Snug Harbor Lane  
Newport News, VA 23606

Date:05-21-08  
Time of Day:9.00 AM  
Ambient Temperature:65 degrees  
Wind Speed:10 MPH  
Relative Humidity:45%


## Dual-View Imaging Report



Location Floor: 1st Floor

Observations:  
Radiant ceiling heat in the way of HVAC return.


## Dual-View Imaging Report



Location Floor: 1st Floor  
Location Room: 1st Floor hall

Observations:  
No HVAC to be installed in 1st floor hall.


## Dual-View Imaging Report



Location Floor: 1st Floor Hall  
Location Room: 1st floor office

Observations:  
Wood beams over top Radiant ceiling.

## Dual-View Imaging Report



Location Floor: 1st Floor Hall  
Location Room: 1st floor office

**Observations:**  
Relocate return to avoid radiant ceiling loops.